Hard & Ware



T&RSET3-RR1 AB

Specification:

Solid brass Turn and Release Set With 5mm Spindle

Finish:


All Standard Finishes avaliable

Included:

X1 Turn & Release Set 5mm Spindle

Care Instructions:

Clean wipe with damp cloth. Avoid using any chemicals. Please note all living finishes are prone to aging & ware



www.hardandware.com



info@hardandware.com