

Hard & Ware



T&RSET4-SR1 AB

Specification:
Solid brass Turn and Release Set
With 5mm Spindle

Finish:
All Standard Finishes available

Included:
X1 Turn & Release Set
5mm Spindle

Care Instructions:
Clean wipe with damp cloth. Avoid using any chemicals.
Please note all living finishes are prone to aging & ware

