Hard & Ware





Specification: Solid brass Turn and Release Set With 5mm Spindle


Finish: All Standard Finishes avaliable


> **Included:** X1 Turn & Release Set 5mm Spindle

Care Instructions: Clean wipe with damp cloth. Avoid using any chemicals. Please note all living finishes are prone to aging & ware









www.hardandware.com

H&W ir

info@hardandware.com